

CASE STUDY

Acomb Conservative Club, York. (Licenced Premises)

OBJECTIVES

We were tasked to carry out a fire risk assessment of the club prior to a fire service inspection taking place.

Operating as a licenced premises the building consisted of 2 floors, the ground main club area and 1st floor residential flat which was occupied at the time of assessment.

SOLUTION

A comprehensive assessment was carried out in which we performed a through audit of the physical premises was carried out as well as all fire safety management procedures.

An action plan was produced for the club and further assistance provided in implementing some of the policies & procedures raised in the assessment.

OUTCOME

We left the club with an up to date fire risk assessment and action in place for them to implement with support from us.

Prioritising the main areas for improvement we assisted the club in implementing their overall schedule of works resulting in a successful fire service audit.



AT A GLANCE

CHALLENGES

- No current fire risk assessment
- Residential premises above
- Fire service audit approaching

OUTCOME

- Up to date fire risk assessment
- Measures in place to protect resident.
- Policies & procedures updated
- Passed fire service audit

VERIFIED REVIEW

"Prompt, friendly service.

Very thorough inspection with sensible, helpful remarks guiding us through areas where we could do better.

Recommended".

Bob Redwood

Acomb Club, York